



13. paint shop - delamination above window




14. paint shop - delamination at light fixture



15. carpenters shop - removed fireproofing adjacent to electrical conduit & junction boxes






16. garage - debris on top of deck hung HVAC equipment



17. garage - water damaged fireproofing on corrugated decking



18. rear hall - general view of overspray on concrete block hallway wall